

## AD Instrumentation - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
24143	Bug	New	Normal	Missing Mutual Exclusion with linked list internals	Robert Santucci	03/06/2020 11:47 AM
23334	Bug	New	Normal	Review request [commit:9d6fb8c32be2b760ee703095242308551c178991: Removed commented syslog(..) calls that where replaced with TRACE.]		09/25/2019 03:06 PM
20450	Bug	New	Normal	The number of samples argument to bpmcli dump does not respect multiple bunches		07/25/2018 03:47 PM
19502	Bug	New	Normal	Excessive delay in first plot, capturing ACNET cursor in window	Elliott McCrory	03/26/2018 02:32 PM
18755	Bug	New	Normal	Plotting Charge, Sigma and Turns does not scale to # Turns Analyzed.	Elliott McCrory	01/19/2018 09:25 AM
18632	Bug	New	Normal	Single turn plot does not work when plotting a turn lower than #1534 and with auto-scaling ON	Elliott McCrory	12/28/2017 09:16 AM
18197	Bug	New	Normal	Why do soft reboots sometime hang?		11/10/2017 10:14 AM
16571	Bug	New	Normal	Flat positions being reported intermittently		05/17/2017 10:36 AM
15282	Bug	New	Normal	Support plotting MDAT transmitter frames via ACNET	Elliott McCrory	01/23/2017 04:07 PM
13462	Bug	New	Normal	57 -97 errors on raw/triggered data channels > 6		08/05/2016 03:14 PM
12809	Bug	New	Normal	F4 node won't boot	John Diamond	05/27/2016 02:20 PM
12754	Bug	New	Normal	slowness of init of 80MHz driver ??	John Diamond	05/23/2016 02:18 PM
11946	Bug	New	Normal	Scale Factor EVENT OVERLAP Error Message	John Diamond	03/11/2016 03:44 PM
11458	Bug	New	Normal	Camera-Switch Instability		01/20/2016 06:12 PM
10094	Bug	New	Normal	Frequent Errors in Live Acquisition		10/02/2015 11:40 AM
10032	Bug	New	Normal	VP94 and HP103 show identical data when plotted together	John Diamond	09/03/2015 11:35 AM
9280	Bug	New	Normal	Turn off interrupts when module is removed.	John Diamond	06/23/2015 01:55 PM
9088	Bug	New	Low	BPMDRO does not release on exit	John Diamond	06/10/2015 11:04 AM
8996	Bug	New	High	Incorrect Horz Histogram window on ROI		06/01/2015 01:03 PM
8946	Bug	New	Normal	Defalut camera?		05/27/2015 09:10 AM
8353	Bug	New	Normal	Java Security Blocks		04/16/2015 10:25 AM
20371	Bug	Assigned	Normal	TSI-148 bridge does not support a master window with multiple data transfer modes	John Diamond	07/23/2018 11:07 AM
12915	Bug	Assigned	High	Missing first injection and other odd behavior with 6+6 slip stacking state	John Diamond	06/27/2016 02:23 PM
9636	Bug	Assigned	Normal	Timing board stops generating TCLK interrupts	John Diamond	11/24/2015 02:23 PM
20473	Bug	Resolved	Normal	Control message queue is not destroyed on shutdown	John Diamond	07/28/2018 08:27 PM
20408	Bug	Resolved	Normal	runtime_error in generated getDeviceInSlot() does not include the driver name	John Diamond	07/23/2018 11:27 AM
20402	Bug	Resolved	Normal	Constants generated for bitfields and enums can cause redeclaration	John Diamond	07/23/2018 10:30 AM
18773	Bug	Resolved	Normal	Single turn plot not showing current data until you toggle single turn -> charge plot -> single turn	David Slimmer	01/26/2018 03:32 PM
18635	Bug	Resolved	High	Necessary LabView parameters are no longer fast time plottable.	David Slimmer	01/08/2018 07:47 AM
16009	Bug	Resolved	Normal	Attenuation tables won't initialize correctly on startup	John Diamond	03/28/2017 03:49 PM
13457	Bug	Resolved	Normal	80MHz digitizer driver should sanity check Nchannels setting	Dennis Nicklaus	08/05/2016 03:03 PM

#	Tracker	Status	Priority	Subject	Assignee	Updated
13456	Bug	Resolved	Normal	80MHz Digitizer requires repeating commands for re-arming twice	Dennis Nicklaus	08/05/2016 03:10 PM
12805	Bug	Resolved	High	SY BPMs won't boot	John Diamond	05/27/2016 02:19 PM
12753	Bug	Resolved	Normal	80MHz board driver could be a little more forgiving of mistakes.	John Diamond	05/23/2016 02:38 PM
9613	Bug	Resolved	Normal	btimemod_device_release does not release alarm interrupt handler	John Diamond	07/14/2015 09:55 AM
8452	Bug	Resolved	High	Input is not in the .gz format	John Diamond	05/12/2015 04:21 PM
8273	Bug	Resolved	High	Picture Stops Updating	John Diamond	05/15/2015 02:06 PM
7065	Bug	Resolved	Normal	Error notifications on multi-screen displays	John Diamond	05/15/2015 02:00 PM
7023	Bug	Resolved	Normal	Remember fit selection between acquisition types		05/15/2015 02:09 PM
6980	Bug	Resolved	Normal	Live Images not working	John Diamond	05/15/2015 01:17 PM
8558	Bug	Feedback	Normal	BBB devices are returning stale data	John Diamond	06/09/2015 02:30 PM
12763	Bug	Accepted	Normal	Raw data device does not support channels	John Diamond	05/25/2016 12:17 PM
8945	Bug	Accepted	High	Error on One-Shot Acquisition	John Diamond	06/01/2015 04:55 PM
8274	Bug	Accepted	Normal	Incorrect amplitude scaling on ROI	John Diamond	05/15/2015 02:03 PM
20432	Bug	Work in progress	Normal	Kernel-level xxxmod_device_get() routine has bbpm250x12 hard-coded	John Diamond	07/24/2018 03:00 PM
12929	Bug	Work in progress	Normal	Pxie Scrapers Clean Up	Roger Tokarek	08/03/2016 03:27 PM
12749	Bug	Work in progress	Low	Cleanup DcctDrv & Calls to DcctDrv	Roger Tokarek	08/03/2016 01:16 PM
11996	Bug	Work in progress	High	Remove Conditional Compilation for Addressing	Roger Tokarek	08/03/2016 10:54 AM